


## Srahmore Peat Repository WL 0199-02

### Environmental Management System Up-Date No. 77 (21/06/17)


#### Environmental Monitoring:

- There were two non-compliance's at SW4 since the last meeting in October 2016. This related to elevated SS, however on both occasions the discharge was contained downstream in the settlement pond preceding SW 104.
- There were no complaints since the last meeting in October 2016.
- There were no incidents since the last meeting in October 2016.

#### Monitoring Results:



#### Munhin 2017 (todate)



## SW4/104/100&101 2017

The average Suspended Solids to date for 2017 is 6.73mg/l at SW 4 and 3.36mg/l at the discharge from the site to the Munhin at SW104. No discharge at SW101 for the period.

SW100 has been removed from the monitoring system, as approved by the EPA as it is not treating any process water from the site operations.

### Srahmore Site Update:

#### Personnel:

##### On Site

		Tractor & General Oper.	0	Environmental	0
BnM (Engineering)	0	Fitters	0	Archaeological	0
Site Admin & Mgt.	1	Electricians	0		
		Site Supervisors	0		
		Excavator & Shovel	0		
				<b>TOTAL EMPLOYED</b>	<b>1</b>

##### Contractors

Security	0	Catering	0		
				<b>TOTAL EMPLOYED</b>	<b>0</b>

##### Off Site

Head Offices Staff	0			BnM (Support)	0
Environmental Officer	1				
				<b>TOTAL EMPLOYED</b>	<b>1</b>

<b>OVERALL TOTAL EMPLOYED</b>	<b>2</b>
-------------------------------	----------

### Srahmore Site Operations:

The site continues to be stabilised and rehabilitated, with the site emissions well below the emission limit values to date in 2017. The water level in Bay 4 was raised to enable more stabilisation of the peat and to facilitate an increased retention time of surface water from the site. This facilitated the retention of more surface water on the bays as required to further stabilize the peat and provide conditions for wetland habitats. Raising of the water in the remainder of the bays has since commenced and is ongoing at present.

**As of the 10th of May 2017 the Srahmore site is compliant with Waste Licence W0199-02.**